

SPA Finalized Actions - 1 July 2019 - 30 September 2019

Codes	
NPR	No Permit Required
NWP	Nationwide Permit
RGP	Regional General Permit
SP	Standard Individual Permit
LOP	Letter of Permission

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2019-00066	NWP	Cactus Ranch Subdivision	Verified Without Special Conditions	Chaffee County	CO
SPA-2019-00067	NWP	Harrington Ditch Diversion Improvement Project	Verified Without Special Conditions	Chaffee County	CO
SPA-2019-00254-SCO	NWP	Virgas Subdivision	Verified Without Special Conditions	Chaffee County	CO
SPA-2019-00222	NPR	Blanca Peak Solar Site	Activity Occurs Entirely on Dry Land (Requires AJD)	Costilla County	CO
SPA-2019-00186	NPR	Cypress Lateral Pipeline Project.	Activity Not Regulated	Eddy County	NM
SPA-2019-00187	NPR	Money Graham Pipeline Project.	Activity Not Regulated	Eddy County	NM
SPA-2019-00188	NPR	China Draw Pipeline Project.	Activity Not Regulated	Eddy County	NM
SPA-2019-00230-LCO	NPR	Salt Creek Midstream, HDD bore	Activity Not Regulated	Eddy County	NM
SPA-2019-00152	NPR	Dancing Wolf Estates Subdivision IV	Activity does NOT impact a potential WOTUS (PJD or No JD)	El Paso County	CO
SPA-2019-00225	NPR	Aspen Meadows Development Isolated Wetlands	Activity does NOT occur in WOTUS (Requires AJD)	El Paso County	CO
SPA-2019-00228	NPR	Wood moor Well No. 21 Transmission Line	Activity does NOT impact a potential WOTUS (PJD or No JD)	El Paso County	CO
SPA-2019-00199	NWP	Anderson Site Home Access Project	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00199	NWP	Anderson Site Home Access Project	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00200	NWP	Venetucci Fisher Canyon Creek Crossing	Verified With Special Conditions	El Paso County	CO
SPA-2019-00146	NWP	Marksheffel Road at Sand Creek Bridge and Structures Addition Project	Verified With Special Conditions	El Paso County	CO
SPA-2019-00210	NWP	Monument Branch Stream Restoration Phase III	Verified With Special Conditions	El Paso County	CO
SPA-2019-00224	NWP	Baird and Knoll Home Access Project	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00200	NWP	Venetucci Fisher Canyon Creek Crossing	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00244-SCO	NWP	Mullins/Poenitsch Subdivision	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00244-SCO	NWP	Mullins/Poenitsch Subdivision	Verified Without Special Conditions	El Paso County	CO
SPA-2019-00146	RGP	Marksheffel Road at Sand Creek Bridge and Structures Addition Project	Verified With Special Conditions	El Paso County	CO
SPA-2019-00209-SCO	NPR	Yevoli Cobblestone Pit	Activity Occurs Entirely on Dry Land (Requires AJD)	Fremont County	CO
SPA-2019-00205-LCO	NPR	Heredia Community Ditch Association diversion dam improvments	Activity Exempt	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00203-LCO	NWP	NFSR 613/614 Maintenance at West Fork Gila River	Verified Without Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00194	NWP	Bill Evans Lake Aquatic Habitat Improvement Project.	Verified With Special Conditions	Grant County	NM
SPA-2019-00248-SCO	NPR	Derry #3 Water Diversion Structure Rehabilitation	Activity Exempt	Lake County	CO
SPA-2019-00245-SCO	RGP	UARRP Lake Fork of the Arkansas River	Verified Without Special Conditions	Lake County	CO
SPA-2019-00180	NPR	Flume Canyon Bar Ditch Restoration project.	Activity Not Regulated	Lincoln County	NM
SPA-2019-00168	NWP	Cedar Creek Culvert project.	Verified With Special Conditions	Lincoln County	NM
SPA-2019-00234-ABQ	NWP	Village of Ruidoso Grindstone Canyon Wetlands Project in Lincoln County, New Mexico	Verified With Special Conditions	Lincoln County	NM
SPA-2018-00034-ABQ	SP	Village of Ruidoso Sanitary Sewer Rehabilitation Project in Lincoln County, New Mexico	Withdrawn By Applicant	Lincoln County	NM
SPA-2019-00204-LCO	NPR	Stateline Crude, LLC. Pecos River crossing	Activity Not Regulated	Loving County	TX
SPA-2019-00124	NWP	Crystal Brown residential development, Pinedale, NM	Verified Without Special Conditions	McKinley County	NM
SPA-2007-00564-DUR	NPR	Wayne Gilmore, bank stabilization repair, Rio Grande River, South Fork, CO	Activity Exempt	Mineral County	CO
SPA-2019-00219	NWP	NMDoT/NM 518 La Cueva Bridge Replacement-Bridge 6288	Verified With Special Conditions	Mora County	NM
SPA-2019-00232	NWP	Morphy Lake boat ramp extension	Verified With Special Conditions	Mora County	NM
SPA-2019-00229	NWP	Preakness and Sendero Pipeline Project.	Verified With Special Conditions	Reeves County	TX
SPA-2010-00482-ABQ	NPR	Acequia del Rincon, Irrigation System Repairs, Embudo Creek, Embudo, NM	Activity Exempt	Rio Arriba County	NM
SPA-2019-00155	NWP	USFS restoration project Upper San Antonio Watershed	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00189	NWP	Jicarilla Apache Restoration project on Amargo Creek	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00201	NWP	Carson NF McSimms Fed 30-4-23-24 well pad and pipeline locations	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00206	NWP	Carson NF McSimms Fed 30-4-26-25 well pad and pipeline locations	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00231-ABQ	RGP	City of Espanola, N. Prince Street Low Water Crossing	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00195	NWP	BLM Farmington - La Plata River oil leak analysis and remediation	Withdrawn	San Juan County	NM
SPA-2019-00217	NWP	Kevin Ashley low water crossing on Estes Arroyo	Verified Without Special Conditions	San Juan County	NM
SPA-2019-00255	NPR	Gallinas River low water crossing replacement	Activity Exempt	San Miguel County	NM
SPA-2019-00212	NWP	Tecolote Bridge maintenance	Withdrawn	San Miguel County	NM
SPA-2019-00235-ABQ	NWP	Beaver Creek Restoration Project	Verified With Special Conditions	San Miguel County	NM
SPA-2019-00216	NWP	NMDoT/Culvert Erosion Repair-US 550 MP 44.1	Provisional Verification	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00207	RGP	SSCAFCA Lomitas Negras arroyo	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00207	SP	SSCAFCA Lomitas Negras arroyo	Withdrawn To Become A General Permit (RGP, PGP, NWP)	Sandoval County	NM
SPA-2019-00213-ABQ	NWP	Cielo de Oro Culvert Maintenance	Verified Without Special Conditions	Santa Fe County	NM
SPA-2019-00221-ABQ	NWP	Eddy Road Low-Water Crossing Replacement	Withdrawn	Santa Fe County	NM
SPA-2019-00052	NWP	NM 152 Bridge Replacement Project.	Verified With Special Conditions	Sierra County	NM
SPA-2019-00164-ABQ	NWP	Transwestern Pipeline Company, Pipeline Exposure and Erosion Repair, Section 7, MP 17.3	Withdrawn To Become A General Permit	Socorro County	NM
SPA-2019-00164-ABQ	RGP	Transwestern Pipeline Company, Pipeline Exposure and Erosion Repair, Section 7, MP 17.3	Verified With Special Conditions	Socorro County	NM
SPA-2009-00520-ABQ	SP	Bosque del Apache NWR Sediment Plug and River Restoration Project	Issued With Special Conditions	Socorro County	NM
SPA-2018-00383-ABQ	NPR	Roxanne George Shed	Withdrawn	Taos County	NM
SPA-2018-00178-ABQ	NWP	Frank Crews Bank Stabilization Rio Grande Del Rancho	Withdrawn For Lack Of Applicant Response	Taos County	NM
SPA-2019-00181	NWP	U.S. Forest Service/Comanche Creek Watershed Stream Restoration-Vidal Creek Sites 7 & 8	Verified With Special Conditions	Taos County	NM
SPA-2019-00181	NWP	U.S. Forest Service/Comanche Creek Watershed Stream Restoration-Vidal Creek Sites 7 & 8	Verified Without Special Conditions	Taos County	NM
SPA-2019-00181	NWP	U.S. Forest Service/Comanche Creek Watershed Stream Restoration-Vidal Creek Sites 7 & 8	Verified Without Special Conditions	Taos County	NM
SPA-2019-00193-ABQ	NWP	Chevron Questa Mine Mitigation, Wetland Restoratoin	Withdrawn By Applicant	Taos County	NM
SPA-2019-00193-ABQ	NWP	Chevron Questa Mine Mitigation, Wetland Restoratoin	Withdrawn	Taos County	NM
SPA-2019-00147-ABQ	NWP	Questa Mine Mitigation	Verified With Special Conditions	Taos County	NM
SPA-2019-00190	NWP	Transwestern Pipeline erosion repair Rio Puerco crossing	Verified Without Special Conditions	Valencia County	NM
SPA-2019-00185	RGP	Transwestern Pipeline repair Socorro County	Verified With Special Conditions	Valencia County	NM