SPA Finalized Actions - 1 April 2019 - 30 June 2019

Codes	
NPR	No Permit Required
NWP	Nationwide Permit
RGP	Regional General Permit
SP	Standard Individual Permit
LOP	Letter of Permission

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2019-00088	NPR	SPA 2019-088 I-40 and Zuzax Interchange Tijeras Creek Box Culvert	Verified With Special Conditions	Bernalillo County	NM
SPA-2019-00130	NWP	SPA-2019-030 Water Line to Escondido Reservoir across Tijeras Arroyo	Permit Required	Bernalillo County	NM
SPA-2019-00141	NWP	SPA2019-141 Tijeras Sewer pipe	Activity Occurs Entirely on Dry Land (Requires AJD)	Bernalillo County	NM
SPA-2018-00258	NWP	Bear Canyon Stabilization	Verified With Special Conditions	Bernalillo County	NM
SPA-2019-00122	NPR	Ben Lilly Campground Bank Armoring Project.	Verified With Special Conditions	Catron County	NM
SPA-2017-00165-SCO	SP	Two Rivers Planned Development	Procedure Complete	Chaffee County	CO
SPA-2017-00166-SCO	SP	City of Salida South Arkansas River Trail Extension	Procedure Complete	Chaffee County	CO
SPA-2019-00039-ABQ	NPR	Continental Divide Solar/Bluewater NM Solar Project	Verified Without Special Conditions	Cibola County	NM
SPA-2019-00139-ABQ	NWP	USFS, FR 1920 North Point Road Crossing Hardening	Verified With Special Conditions	Colfax County	NM
SPA-2019-00115	NPR	Breakwater Pecos River Fresh Water Pipeline Project.	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NPR	Sendero Carlsbad Gateway	Verified With Special Conditions	Eddy County	NM
SPA-2018-00360-LCO	NPR	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NPR	Sendero Carlsbad Gateway	Verified With Special Conditions	Eddy County	NM
SPA-2018-00360-LCO	NPR	Sendero Carlsbad Gateway	Verified With Special Conditions	Eddy County	NM
SPA-2018-00360-LCO	NPR	Sendero Carlsbad Gateway	Verified With Special Conditions	Eddy County	NM
SPA-2018-00360-LCO	NWP	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NWP	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NWP	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NWP	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2018-00360-LCO	NWP	Sendero Carlsbad Gateway	Activity Not Regulated	Eddy County	NM
SPA-2019-00162	NWP	Salt Creek Midstream Pipeline Project.	Activity Not Regulated	Eddy County	NM
SPA-2019-00120	NPR	Work Package 2 of the I-25 South Gap Project, El Paso County Colorado	Verified With Special Conditions	El Paso County	CO
SPA-2019-00133	NWP	Notice - Construction Materials Reclamation Permit Application, Luther Huddleson, File No. M-2019-009	Permit Requirement Unknown	El Paso County	CO
SPA-2015-00428-SCO	NWP	Sterling Ranch Residential Development Project, El Paso County, Colorado	Verified Without Special Conditions	El Paso County	CO
SPA-1998-30063-SCO	NWP	REGENCY PARK DEVELOPMENT - TRIVIEW METR	Issued With Special Conditions	El Paso County	CO
SPA-1998-30063-SCO	NWP	REGENCY PARK DEVELOPMENT - TRIVIEW METR	Extension of Time Authorized	El Paso County	CO
SPA-2019-00157	NWP	CDOT - State Highway 21 (Powers Blvd.) and Research Parkway Interchange.	Verified With Special Conditions	El Paso County	CO
SPA-2018-00182	NWP	Forest Lakes Subdivision Access Road	Verified With Special Conditions	El Paso County	CO
SPA-2019-00108	NPR	New Mexico New Model Canal Project.	Activity Exempt	Hidalgo County	NM
SPA-2019-00145	NWP	Hoehne Stream Gauge	Withdrawn To Become A General Permit	Las Animas County	CO
SPA-2019-00145	RGP	Hoehne Stream Gauge	Verified Without Special Conditions	Las Animas County	CO
SPA-2019-00084-ABQ	NPR	Culvert Installation within Eagle Creek at 317 Eagle Creek Road in Ruidoso, New Mexico	Verified With Special Conditions	Lincoln County	NM
SPA-2019-00094	NPR	2019-094 Ruidoso Erosion Control and Habitat Restoration	Verified With Special Conditions	Lincoln County	NM
SPA-2014-00094-ABQ	NWP	The Close Road Bridge Replacement Project in Lincoln County, New Mexico	Verified With Special Conditions	Lincoln County	NM
SPA-2011-00512-ABQ	NWP	Water Canyon Culvert Replacement and Utility Line Crossings	Procedure Complete	Los Alamos County	NM
SPA-2011-00253-ABQ	NWP	Sandia Canyon TA-72 Shooting Range Stormwater Management	Procedure Complete	Los Alamos County	NM
SPA-2016-00179-ABQ	NWP	Los Alamos National Laboratory Boundary Protection and Watershed Enhancement SEP	Procedure Complete	Los Alamos County	NM
SPA-2016-00179-ABQ	NWP	Los Alamos National Laboratory Boundary Protection and Watershed Enhancement SEP	Procedure Complete	Los Alamos County	NM
SPA-2016-00179-ABQ	NWP	Los Alamos National Laboratory Boundary Protection and Watershed Enhancement SEP	Procedure Complete	Los Alamos County	NM
SPA-2019-00080	NPR	Crownpoint N9 Wash Out Exposed Gas Line Project, (NTUA) ATF	Verified Without Special Conditions	McKinley County	NM
SPA-2016-00356	NWP	Emergency Bank Stabilization, I 40 Marker 11 (Salt Water Wash)	Procedure Complete	McKinley County	NM
SPA-2019-00090	NPR	Rio Mora NWR Stream Restoration	Verified With Special Conditions	Mora County	NM
SPA-2019-00135-ABQ	NWP	Alcone Violation-Mora River	Withdrawn	Mora County	NM
SPA-2018-00091-ABQ	NWP	Unauthorized Activity at the Canada Del Oso Ranch in Mora County, New Mexico	Verified With Special Conditions	Mora County	NM
SPA-2019-00137	NWP	Flood Repair at Fitzpatrick Property	Permit Required	Pueblo County	CO
SPA-2019-00137	RGP	Flood Repair at Fitzpatrick Property	Verified Without Special Conditions	Pueblo County	CO
SPA-2019-00109-ABQ	NPR	Union Pacific Railroad/Train Derailment South of Logan-Canadian River	Verified With Special Conditions	Quay County	NM
SPA-2019-00111-ABQ	NPR	NMDoT/NM 96 Bridge 5637 Replacement	Verified Without Special Conditions	Rio Arriba County	NM
SPA-2017-00111-ABQ	NPR	Juan Medina Road and Highway 76 Site Preparation for Church	Permit Required	Rio Arriba County	NM
SPA-2018-00102-ABQ	NPR	Embudo Creek Relocation in Dixon, NM	Withdrawn For Lack Of Applicant Response	Rio Arriba County	NM
SPA-2019-00116-ABQ	NPR	Vallecitos Reecy Stream Habitat Restoration, Rio Arriba County, NM	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00126	NWP	EPIC Energy - Brown #202 bank stabilization	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00086-ABQ	NWP	Weidner Drainage Ditch Relocation, Rio Arriba County	Activity Occurs Entirely on Dry Land (Requires AJD)	Rio Arriba County	NM
SPA-2017-00111-ABQ	NWP	Juan Medina Road and Highway 76 Site Preparation for Church	Verified With Special Conditions	Rio Arriba County	NM
SPA-2019-00154	NWP	Chama Wastewater Pond Removal	No Permit Required	Rio Arriba County	NM
SPA-2015-00067	RGP	County Road 155 Bridge and Two Low Water Crossings	Procedure Complete	Rio Arriba County	NM
SPA-2015-00067	RGP	County Road 155 Bridge and Two Low Water Crossings	Procedure Complete	Rio Arriba County	NM
SPA-2013-00569-ABQ	RGP	McCurdy Road Llano Ditch Culvert Extension	Procedure Complete	Rio Arriba County	NM
SPA-2017-00073-ABQ	RGP	US 84 MM 232.7 Embankment Erosion at Canjilon Creek	Procedure Complete	Rio Arriba County	NM
SPA-2019-00121	NPR	Westwater Arroyo Surface Water Monitoring Station	Verified Without Special Conditions	San Juan County	NM
SPA-2019-00123	NPR	Bridge 8118 (5-Mile Bridge) Bank Stabilization, San Juan County, NM	Verified Without Special Conditions	San Juan County	NM
SPA-2019-00128	NWP	Kinder Morgan Cortez Pipeline washout MP 135, San Juan County, NM	Withdrawn For Lack Of Applicant Response	San Juan County	NM
SPA-2019-00131	NWP	Kevin Ashley bank stabilization Aztec, NM	Withdrawn	San Juan County	NM
SPA-2019-00134	NWP	Steve Martinez Rabbit Arroyo bank stabilization, Aztec, NM	Withdrawn	San Juan County	NM
SPA-2019-00136	NWP	Nenahnezad AML Subsidence, San Juan County, New Mexico	Activity Occurs Entirely on Dry Land (Requires AJD)	San Juan County	NM
SPA-2019-00140	NWP	Ranchmans-Terrell in-stream irrigation diversion, Flora Vista, NM	Activity Exempt	San Juan County	NM
SPA-2019-00151	NWP	Shiprock Administrative Reserve North Parcel - BIA Cleanup, Shiprock, NM	Activity Occurs Entirely on Dry Land (Requires AJD)	San Juan County	NM
SPA-2019-00158	NWP	San Juan River Dineh Water Users, Inc. 40-inch steel irrigation siphon replacement	No Permit Required	San Juan County	NM
SPA-2019-00158	NWP	San Juan River Dineh Water Users, Inc. 40-inch steel irrigation siphon replacement	Activity Exempt	San Juan County	NM
SPA-2019-00091-ABQ	NPR	County of San Miguel/El Camino River Walk-Gallinas River	Verified Without Special Conditions	San Miguel County	NM
SPA-2019-00161	NWP	ENMR Telephone fiber optic project	Permit Requirement Unknown	San Miguel County	NM
SPA-2019-00100-ABQ	NPR	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00118-ABQ	NPR	Temporary Repairs to Chessman Road at a Crossing of an Ephemeral Tributary to the Los Montoyas Arroyo in Rio Rancho, Sandoval County, New Mexico	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00119-ABQ	NPR	Valles Caldera National Preserve, La Jara Creek and Wetland Restoration Project	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00127	NWP	Hitt Violation/Road Crossing-Placitas	Restoration Order	Sandoval County	NM
SPA-2015-00200-ABQ	NWP	Kinder Morgan CO2 Co./Pipeline Protection MP 163-Penistaja Arroyo	Withdrawn For Lack Of Applicant Response	Sandoval County	NM
SPA-2019-00159	NWP	A-1 Storage bank stabilization, Rio Rancho, Sandoval County, NM	Verified With Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00159	NWP	A-1 Storage bank stabilization, Rio Rancho, Sandoval County, NM	Permit Required	Sandoval County	NM
SPA-2019-00100-ABQ	NWP	BOR/Navajo-Gallup Water Transmission (Part 2)	Verified Without Special Conditions	Sandoval County	NM
SPA-2019-00127	RGP	Hitt Violation/Road Crossing-Placitas	Procedure Complete	Sandoval County	NM
SPA-2019-00132-ABQ	NWP	LANL, Monitoring Well (PAO-4) Removal, Santa Fe County, NM	Verified With Special Conditions	Santa Fe County	NM
SPA-2019-00142	NWP	2019-142 Agua Fria Wastewater Improvement	Permit Required	Santa Fe County	NM
SPA-2019-00148-ABQ	NWP	Acequia Barranco Alto, Rio Nambe, Temporary Diversion Structure	Withdrawn Due To No Permit Required (NPR)	Santa Fe County	NM
SPA-2019-00149-ABQ	NWP	Acequia Ancon de Jacona, Temporary Diversion Structure	Withdrawn Due To No Permit Required (NPR)	Santa Fe County	NM
SPA-2019-00150-ABQ	NWP	Acequia de la Otra Banda, Rio Pojoaque, Repair to Ojitos Water Gallery	Activity Exempt	Santa Fe County	NM
SPA-2019-00149-ABQ	NWP	Acequia Ancon de Jacona, Temporary Diversion Structure	Activity Exempt	Santa Fe County	NM
SPA-2019-00148-ABQ	NWP	Acequia Barranco Alto, Rio Nambe, Temporary Diversion Structure	Activity Exempt	Santa Fe County	NM
SPA-2019-00087-ABQ	NPR	Taos Ski Valley, Inc., Kachina Mountain Facilities Lake Fork Diversion Improvement Project	Verified With Special Conditions	Taos County	NM
SPA-2019-00144	NWP	Van Houten Friend Driveway La Semilla Road	Exceeded Corps Review Time Limit, Verified By Default	Taos County	NM
SPA-2019-00110-LCO	NPR	NM 6 Bridge Construction and Removal over the Rio Grande	Verified With Special Conditions	Valencia County	NM
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Permit Required	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Withdrawn Due To No Permit Required (NPR)	Ward County	TX
SPA-2018-00236-LCO	NWP	Lockridge Extension Pipeline	Verified Without Special Conditions	Ward County	TX