

Nationwide Permit Actions
July 1 - September 30, 2015

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2015-00107-ABQ	NWP	Sulphur Creek Wetlands Restoration Project in the Valles Caldera National Preserve, Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00117	NWP	N57 Erosion Repair @ Station 5+542	Verified Without Special Conditions	San Juan	NM
SPA-2015-00061	NWP	Santa Rosa Waterline Repair Project	Verified With Special Conditions	Guadalupe	NM
SPA-2015-00085	NWP	Mundo Ranch Phase 4 Drainage Improvements	Verified Without Special Conditions	Rio Arriba	NM
SPA-2015-00148-SCO	NWP	BNSF Railway Bridge 218.83 Replacement, Rule Creek, Las Animas, Bent County, Colorado	Verified Without Special Conditions	Bent	CO
SPA-2015-00085	NWP	Mundo Ranch Phase 4 Drainage Improvements	Verified Without Special Conditions	Rio Arriba	NM
SPA-2015-00162	NWP	NM 95 Bridge 5727 Repair	Verified With Special Conditions	Rio Arriba	NM
SPA-2012-00523	NWP	Red Lake Dam Maintenance	Verified Without Special Conditions	McKinley	NM
SPA-2015-00170	NWP	Russell Sand and Gravel Bank Stabilization on Rio Brazos	Verified Without Special Conditions	Rio Arriba	NM

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2014-00292-ABQ	NWP	The Southern Sandoval County Arroyo and Flood Control Authority Upper SLO Dam Project	Verified With Special Conditions	Sandoval	NM
SPA-2015-00180	NWP	N52 Gravel Project	Verified Without Special Conditions	McKinley	NM
SPA-2015-00188-LCO	NWP	Dripping Springs Road and Baylor Canyon Road Improvement Project	Verified With Special Conditions	Dona Ana	NM
SPA-2015-00187	NWP	ConocoPhillips Jaramillo Canyon Road Crossing Project in Rio Arriba County, NM	Verified With Special Conditions	Rio Arriba	NM
SPA-2015-00083-ABQ	NWP	Kirtland Air Force Base KUMMSC Bridge Bypass Coyote Arroyo	Verified Without Special Conditions	Bernalillo	NM
SPA-2015-00199	NWP	Gloe Driveway Creek Crossing	Withdrawn For Enforcement Action	Saguache	CO
SPA-2015-00047-ABQ	NWP	Electrical System Upgrades at Bandelier National Monument in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2012-00401	NWP	Weir install; Govt Spring; Rio Bonito; BLM; Lincoln Co	Verified With Special Conditions	Lincoln	NM
SPA-2015-00229-LCO	NWP	ASARCO Smelter Remediation	Verified With Special Conditions	El Paso	TX
SPA-2015-00228	NWP	Three Mile Canyon Monitoring Area Water Control Measures	Verified Without Special Conditions	Los Alamos	NM

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2015-00220-LCO	NWP	Courchesne Phase 1A Levee Improvements	Verified Without Special Conditions	Dona Ana	NM
SPA-2015-00188-LCO	NWP	Dripping Springs Road and Baylor Canyon Road Improvement Project	Verified With Special Conditions	Dona Ana	NM
SPA-2015-00047-ABQ	NWP	Electrical System Upgrades at Bandelier National Monument in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00239-LCO	NWP	Continental Mine Haul Road Project Grant County, New Mexico	Verified Without Special Conditions	Grant	NM
SPA-2015-00240	NWP	Rio Nambe Utility Access Road Embankment	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00242	NWP	LA-SMA-2.1 Stormwater Controls	Verified Without Special Conditions	Los Alamos	NM
SPA-2015-00246	NWP	Nambe NP101 Roadway Maintenance	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00273	NWP	Erosion Repair and Pipeline Protection Activities Section 7 MP 52.8	Verified Without Special Conditions	Valencia	NM
SPA-2015-00048-ABQ	NWP	2nd Street Bridge Replacement, Grants, Cibola County	Verified Without Special Conditions	Cibola	NM
SPA-2015-00206-LCO	NWP	Alpha Crude Connector (ACC) Pipeline Project	Verified Without Special Conditions	Eddy	NM
SPA-2015-00276-SCO	NWP	Buena Vista Public Library Bank Stabilization Project	Verified Without Special Conditions	Chaffee	CO

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2015-00277-SCO	NWP	Rainbow Falls Recreation Area, Fountain Creek, Manitou Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00272-LCO	NWP	Deep Creek Stream Restoration	Verified With Special Conditions	Catron	NM
SPA-2015-00281-SCO	NWP	Senter Property Bank Stabilization, Cottonwood Creek, Buena Vista, Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	CO
SPA-2015-00285-LCO	NWP	West Fork of the Gila River Emergency Bank Stabilization Project, FHWA-CFLHD	Verified With Special Conditions	Catron	NM
SPA-2015-00290	NWP	Lodge Lake Outlet Weir Replacement	Verified Without Special Conditions	Mineral	CO
SPA-2015-00291	NWP	Lodge Lake Outfall Ditch Channel Stabilization	Verified Without Special Conditions	Mineral	CO
SPA-2015-00293-LCO	NWP	Lateral 1 and Lateral 2 Pipeline Project in Lea County, New Mexico	Verified Without Special Conditions	Lea	NM
SPA-2015-00297-SCO	NWP	Manitou Springs Flood Remediation, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00302-LCO	NWP	Otero County Timberon Culvert Replacement Project	Verified Without Special Conditions	Otero	NM

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2015-00303-ABQ	NWP	Enterprise Products Bank Stabilization for Pipeline Protection in the Arroyo Ojito on Pueblo of Zia Lands in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00085	NWP	Mundo Ranch Phase 4 Drainage Improvements	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00201	NWP	Lake Humphreys Dredging	Verified With Special Conditions	Mineral	CO
SPA-2015-00054-ABQ	NWP	City of Rio Rancho Idalia Road Construction Project In Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00274	NWP	Sevilleta NWR River Mile 130-99 Habitat Restoration	Verified With Special Conditions	Socorro	NM
SPA-2015-00246	NWP	Nambe NP101 Roadway Maintenance	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00310-SCO	NWP	Rainbow Falls Debris Catchment Basin	Verified Without Special Conditions	El Paso	CO
SPA-2015-00319-ABQ	NWP	Nambe Falls Recreation Area Picnic Structures Repair and Replacement	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00311-SCO	NWP	Chipita Park Box Culvert Repair	Verified Without Special Conditions	El Paso	CO
SPA-2015-00199	NWP	Gloe Driveway Creek Crossing	Verified Without Special Conditions	Saguache	CO

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2015-00312-SCO	NWP	Jones Road Culvert Repair	Verified Without Special Conditions	El Paso	CO
SPA-2015-00326	NWP	CDOT Conejos River Bridge	Verified With Special Conditions	Conejos	CO
SPA-2015-00323-LCO	NWP	Pueblo Park Culvert Repair	Verified Without Special Conditions	Catron	NM
SPA-2015-00328-SCO	NWP	US 24 Culvert maintenance at MM 206.6 in Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	CO
SPA-2015-00318-ABQ	NWP	Chaco 161 274 Well Pad Access Road and Pipeline	Verified Without Special Conditions	Rio Arriba	NM
SPA-2015-00025	NWP	Quay County Road 63 Cemetery Road Culvert Replacement	Verified With Special Conditions	Quay	NM
SPA-2015-00337-ABQ	NWP	NM Department of Game and Fish, Mora Fishing Access Area Fish Habitat Improvement Project, Terrero, NM	Verified With Special Conditions	San Miguel	NM
SPA-2015-00339-SCO	NWP	Unauthorized Activity - Earthen Dam at Fillmore Street and Mesa Road	Verified Without Special Conditions	El Paso	CO
SPA-2015-00228	NWP	Three Mile Canyon Monitoring Area Water Control Measures	Verified Without Special Conditions	Los Alamos	NM
SPA-2015-00344-LCO	NWP	Recoat and Restore Cover on El Paso Natural Gas Line No. 2000 at Wild Horse Draw	Verified Without Special Conditions	Culberson	TX
SPA-2011-00049-SCO	NWP	West 11th Street Bridge Replacement and Utility Relocation, Pueblo, Colorado	Verified Without Special Conditions	Pueblo	CO

Nationwide Permit Actions
July 1 - September 30, 2015

SPA-2015-00351-SCO	NWP	Colorado Springs Utilities - Pinello Ranch Mitigation Site	Verified With Special Conditions	El Paso	CO
SPA-2015-00352-SCO	NWP	Tom Puskas - road crossing	Verified Without Special Conditions	El Paso	CO
SPA-2015-00353-SCO	NWP	Cherokee Metropolitan District Jimmy Camp Creek Project	Verified Without Special Conditions	El Paso	CO
SPA-2015-00358-SCO	NWP	CR 220 Culvert Installation, Grape Creek, Westcliffe, Custer County, Colorado	Verified Without Special Conditions	Custer	CO
SPA-2015-00364	NWP	Town of Crestone - Alder Street Culvert Maintenance	Verified Without Special Conditions	Saguache	CO
SPA-2015-00365-SCO	NWP	Williams Canyon Box Culvert Sediment Removal, Fountain Creek, Manitou Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO