

NATIONWIDE PERMIT ACTIONS
JUL - SEPT 2014

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2014-00350-SCO	NWP	Pocket Wave Project, Buena Vista Whitewater Park, Arkansas River, Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	CO
SPA-2011-00511-SCO	NWP	Mendicino Pond, North Fork of South Arkansas River, Salida, Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	CO
SPA-2014-00284-SCO	NWP	Glen Eyrie Sanitary Sewer Realignment, Camp Creek Crossings, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2014-00305-SCO	NWP	Colorado Springs Utilities - 33rd Pump Station maintenance	Verified Without Special Conditions	El Paso	CO
SPA-2014-00317-SCO	NWP	I-25/US24/Cimarron Street Interchange Reconstructon	Verified Without Special Conditions	El Paso	CO
SPA-2014-00317-SCO	NWP	I-25/US24/Cimarron Street Interchange Reconstructon	Verified Without Special Conditions	El Paso	CO
SPA-2014-00354-SCO	NWP	Owens Hall Diversion Dam and Fish Passage, Clear Spring Ranch, Fountain Creek, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2005-00131-SCO	NWP	COLO. SPGS UTILITIES - Southern Delivery System	Verified Without Special Conditions	El Paso	CO
SPA-2014-00361-SCO	NWP	CDOT Project US 24 Bridge Rehabilitation I-17-A	Verified Without Special Conditions	El Paso	CO
SPA-2013-00087-SCO	NWP	I-25 North Design Build Improvements, Highway Corridor btw Gleneagle and USAFA, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2010-00319	NWP	Forest View Acres Water District Waterline Replacement	Verified With Special Conditions	El Paso	CO
SPA-2014-00417-SCO	NWP	City of Colorado Springs 25th Street Project	Verified Without Special Conditions	El Paso	CO
SPA-2014-00428-SCO	NWP	Wolf Ranch Gas Main Protection, Cottonwood Creek Tributary, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO

SPA-2012-00405-SCO	NWP	Parkdale Granite Quarry, Front Range Aggregates, Tallahassee Creek, Fremont County, Colorado	Withdrawn By Applicant	Fremont	CO
SPA-2014-00418-SCO	NWP	Spanish Peaks Scout Ranch	Verified Without Special Conditions	Huerfano	CO
SPA-2014-00318-SCO	NWP	UAARP Outward Bound Reach Channel and Floodplain Restoration Project	Withdrawn To Become A General Permit (RGP, PGP)	Lake	CO
SPA-2014-00338-SCO	NWP	Wiepking Fullerton Energy Big Dry Creek Low Water Crossing	Verified Without Special Conditions	Lincoln	CO
SPA-2014-00319-SCO	NWP	Cuerna Verde Association New Point of Diversion	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00362-SCO	NWP	CDOT Project STA 050A-022; US 50 East Bound Lane and Intersection Improvements, Pueblo West	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Withdrawn By Applicant	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00374-SCO	NWP	Colorado Parks & Wildlife - habitat structures - maintenance	Verified Without Special Conditions	Pueblo	CO
SPA-2014-00378-SCO	NWP	El Centro Del Quinto Sol Park and Trails Project, Fountain Creek, Pueblo, Pueblo County, Colorado	Verified Without Special Conditions	Pueblo	CO

SPA-2014-00071	NWP	Jeffery McCullough	Verified Without Special Conditions	Rio Grande	CO
SPA-2014-00434-SCO	NWP	Willow Creek Park - septic system construction	Verified Without Special Conditions	Rio Grande	CO
SPA-2013-00558	NWP	John and Carol Wagner	Verified Without Special Conditions	Saguache	CO
SPA-2010-00586	NWP	Gregg Sease Partial Filling of Ponds, Saguache Creek, Saguache County, Colorado	Verified Without Special Conditions	Saguache	CO
SPA-2014-00392	NWP	John and Carol Wagner - NRCS	Verified Without Special Conditions	Saguache	CO
SPA-2014-00315-SCO	NWP	Four-mile Creek Restoration, Teller County, Colorado	Verified With Special Conditions	Teller	CO
SPA-2014-00369-SCO	NWP	Fountain Creek at Walmart Emergency Bank Stabilization Project	Verified Without Special Conditions	Teller	CO
SPA-2014-00353-LCO	NWP	Emergency Response Federally Owned Roads Program NM ERFO 28(2) Indian Creek Emergency Response Culvert Replacement Project-Nationwide 14 Permit Application	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00389-LCO	NWP	Copper Creek-Forest Road 119 Maintenance	Verified Without Special Conditions	Catron	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM

[illegible]

[illegible]

[illegible]

[illegible]

SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2014-00206	NWP	N55(3)1,2&4 Alamo to I-40 Highway Reconstruction	Verified Without Special Conditions	Cibola	NM
SPA-2009-00503-ABQ	NWP	Vermejo Park Ranch Dillon Canyon Restoration	Verified Without Special Conditions	Colfax	NM
SPA-2014-00394-ABQ	NWP	ARP Raton Expansion Project, Canadian River Pipeline Crossing, Vermejo Park Ranch, New Mexico	Verified With Special Conditions	Colfax	NM
SPA-2014-00421-LCO	NWP	Erosion Repair and Pipeline Protection, Eddy County, NM	Verified With Special Conditions	Eddy	NM
SPA-2014-00403-LCO	NWP	Lea County Lateral Pipeline in Lea County, New Mexico, and Andrews and Gaines Counties, Texas	Verified Without Special Conditions	Lea	NM
SPA-2014-00403-LCO	NWP	Lea County Lateral Pipeline in Lea County, New Mexico, and Andrews and Gaines Counties, Texas	Verified Without Special Conditions	Lea	NM

SPA-2014-00405-ABQ	NWP	Upper Sandia Canyon Riparian Restoration, ENV-DO-14-0235	Verified Without Special Conditions	Los Alamos	NM
SPA-2014-00433-ABQ	NWP	TA-39 Point 6 Firing Site - Ancho Site Monitoring Area 6, Solid Waste Management Unit 39-004(c)	Verified With Special Conditions	Los Alamos	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2013-00581-ABQ	NWP	BNSF Bridge Replacements	Verified Without Special Conditions	McKinley	NM
SPA-2014-00261	NWP	US 491 Reconstruction Project (CN 6100783)	Withdrawn	McKinley	NM
SPA-2014-00273	NWP	El Paso Natural Gas - Line 1200 Erosion Repair Project	Withdrawn For Lack Of Applicant Response	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00090	NWP	US 491 Reconstruction Project (CN 6100785)	Verified With Special Conditions	McKinley	NM
SPA-2014-00224-ABQ	NWP	Coyote Creek State Park Low-Water Crossing	Verified Without Special Conditions	Mora	NM
SPA-2014-00225-ABQ	NWP	Coyote Creek State Park Bridge Repair	Verified Without Special Conditions	Mora	NM
SPA-2014-00295-ABQ	NWP	NMDOT - NM 105 MP 6.7 Culvert Replacment, Rito San Jose, Rociada, Mora County, NM	Verified Without Special Conditions	Mora	NM
SPA-2014-00377-ABQ	NWP	Morphy Lake Preliminary Engineering Investigations, Acequias de la Isla/de la San Jose, Morphy Lake, Mora County, NM	Verified With Special Conditions	Mora	NM

SPA-2014-00242-ABQ	NWP	CR 162 Bridge Replacement	Withdrawn For Lack Of Applicant Response	Rio Arriba	NM
SPA-2014-00263-ABQ	NWP	NM ERFO 600(1), Rt 600/Kee St Bridge Repair	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00269	NWP	Lateral R6	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00340	NWP	Escrito E07-2407	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00339-ABQ	NWP	Rio Ojo Caliente Stream Channel and Bank Restoration	Withdrawn By Applicant	Rio Arriba	NM
SPA-2014-00340	NWP	Escrito E07-2407	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00356-ABQ	NWP	Jaramillo Canyon Road Upgrade Project	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00356-ABQ	NWP	Jaramillo Canyon Road Upgrade Project	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00122	NWP	Canada del Bano Roadway Crossing	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00122	NWP	Canada del Bano Roadway Crossing	Verified Without Special Conditions	Rio Arriba	NM
SPA-2014-00386-ABQ	NWP	Rio San Antonio Bridge, Rio San Antonio, Tres Piedras Ranger District, Carson National Forest, Rio Arriba County, New Mexico	Verified Without Special Conditions	Rio Arriba	NM
SPA-2013-00469	NWP	N5113 Beclabito Roadway Crossing BIA	Verified Without Special Conditions	San Juan	NM
SPA-2013-00548	NWP	Navajo Route N562 Road Repair	Verified Without Special Conditions	San Juan	NM
SPA-2014-00012	NWP	Culvert Pipe Maintenance NR 530	Verified Without Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM

SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified Without Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2012-00254-ABQ	NWP	USBR Navajo-Gallup Water Transmission	Verified With Special Conditions	San Juan	NM
SPA-2014-00207	NWP	NM DOT US Highway 64 Improvement Project Mileposts 58-60.0	Verified With Special Conditions	San Juan	NM
SPA-2014-00243	NWP	Bluffview Power Plant Cooling Tower Discharge Outfall	Verified With Special Conditions	San Juan	NM
SPA-2014-00136	NWP	Southside Mutual Domestic Water Association Proposed Water System Improvements	Withdrawn Due To No Permit Required (NPR)	San Juan	NM
SPA-2014-00276	NWP	Williams Four Corners LLC Trunk K	Withdrawn To Become A General Permit (RGP, PGP)	San Juan	NM
SPA-2013-00109	NWP	Dan Flack at Navajo Dam	Verified Without Special Conditions	San Juan	NM

SPA-2014-00334	NWP	Lybrook M11-2308 Project	Verified Without Special Conditions	San Juan	NM
SPA-2014-00336	NWP	Lybrook H09-2308	Verified Without Special Conditions	San Juan	NM
SPA-2014-00337	NWP	Lybrook I11-2308	Verified Without Special Conditions	San Juan	NM
SPA-2013-00195	NWP	unauthorized Arroyo fill	Verified With Special Conditions	San Juan	NM
SPA-2014-00207	NWP	NM DOT US Highway 64 Improvement Project Mileposts 58-60.0	Verified With Special Conditions	San Juan	NM
SPA-2014-00337	NWP	Lybrook I11-2308	Verified Without Special Conditions	San Juan	NM
SPA-2014-00371	NWP	San Juan Country Club Estates Detention Pond	Withdrawn	San Juan	NM
SPA-2014-00384	NWP	Kiffen Canyon Access Road	Withdrawn	San Juan	NM
SPA-2014-00297-ABQ	NWP	Maintenance of the Northern Boulevard Crossing of the Montoyas Arroyo in Rio Rancho, Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00320-ABQ	NWP	Encana Oil & Gas (U.S.A) Inc. Lybrook E33-2307 Well Pad Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00321-ABQ	NWP	Encana Oil & Gas (USA) Inc. Lybrook P32-2307 Well Pad Project in Sandoval County New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00322-ABQ	NWP	Encana Oil & Gas (USA) Inc. Lybrook L33-2307 Well Pad Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00323-ABQ	NWP	Encana Oil & Gas Inc. Lybrook I30-2306 Well Pad Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00233-ABQ	NWP	Maintenance of a New Mexico Gas Company Pipeline within the Jemez Mountains in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00299-ABQ	NWP	Maintenance Activities Upstream of BIA Route 85 in the Sile Channel at the Pueblo of Santo Domingo in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM

SPA-2014-00346-ABQ	NWP	Encana Oil & Gas (USA) Inc. Lybrook L29-2307 Well Pad Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00347-ABQ	NWP	Encana Oil & Gas (USA) Inc. Lybrook P31-2307 Well Pad Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00213-ABQ	NWP	Channel Realignment and Restoration of the Rio Puerco upstream of the NM 197 Crossing Near the Town of Cuba in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00233-ABQ	NWP	Maintenance of a New Mexico Gas Company Pipeline within the Jemez Mountains in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00233-ABQ	NWP	Maintenance of a New Mexico Gas Company Pipeline within the Jemez Mountains in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013-00061-ABQ	NWP	Black Arroyo Open Space Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00407-ABQ	NWP	BIA Route 90 Emergency Response Culvert Replacement	Verified Without Special Conditions	Sandoval	NM
SPA-2013-00061-ABQ	NWP	Black Arroyo Open Space Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013-00061-ABQ	NWP	Black Arroyo Open Space Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2014-00167-ABQ	NWP	Pueblo Canyon Stabilization Project	Verified Without Special Conditions	Santa Fe	NM
SPA-2014-00291-ABQ	NWP	Buffalo Subdivision Road Construction Project at the Pueblo of Nambe in Santa Fe County, New Mexico	Verified With Special Conditions	Santa Fe	NM
SPA-2014-00335-ABQ	NWP	Pueblo Canyon Grade Control Spurs and E060.1 Gage Revitalization, ENV-DO-14-0175	Verified Without Special Conditions	Santa Fe	NM
SPA-2014-00393-ABQ	NWP	Rio Nambe Sewage Lagoon Bank Stabilization	Verified Without Special Conditions	Santa Fe	NM
SPA-2013-00384-LCO	NWP	Dam Site Boat Ramp Extension	Withdrawn By Applicant	Sierra	NM
SPA-2013-00387-LCO	NWP	Rock Canyon Boat Ramp Expansion	Verified Without Special Conditions	Sierra	NM

SPA-2012-00550-LCO	NWP	Habitat Improvement Project at Elephnat Butte	Verified Without Special Conditions	Sierra	NM
SPA-2014-00296-ABQ	NWP	USFS Carson NF, Grassy Creek Culvert Removal/Low Water Xing, Grassy Creek, Taos County, NM	Verified Without Special Conditions	Taos	NM
SPA-2013-00535-ABQ	NWP	BNSF, Abo Arroyo Tributary, Bridge 7100, Replacement, Torrance County, NM	Verified With Special Conditions	Torrance	NM
SPA-2014-00257-LCO	NWP	Roberto Bustamante Wastewater Treatment Plant Effluent Pipeline to Rio Bosque Wetlands Park	Verified With Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified With Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified With Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2014-00359-LCO	NWP	N. Desert Blvd. Frontage Rd. Improvement Project - El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2014-00382-LCO	NWP	Canutillo Bosque Lift Station and Force Main Project	Verified Without Special Conditions	El Paso	TX
SPA-2014-00435-LCO	NWP	Bridge Maintenance - Texas DOT - El Paso Texas - Artcraft (SH 178)	Verified Without Special Conditions	El Paso	TX

