NATIONWIDE PERMIT ACTIONS OCTOBER - DECEMBER 2013

	Action				
DA Number	Туре	Project Name	Closure Method	County	State
SPA-2013- 00466-SCO	NWP	City of Salida WWTF Waterline Extension Project, Arkansas River, Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	со
SPA-2013- 00487-SCO	NWP	CDOT, Culvert Maintenance Project on US 285 at MM 1265.654 in Poncha Springs	Verified Without Special Conditions	Chaffee	со
SPA-2013- 00501-SCO	NWP	Miller Property - Bank Stabilization, Little Arkansas River, Chaffee Co., Colorado	Verified Without Special Conditions	Chaffee	со
SPA-2013- 00534-SCO	NWP	Little River Ranch Bridge Replacement, South Arkansas River, Poncha Springs, Chaffee County, Colorado	Verified Without Special Conditions	Chaffee	со
SPA-2013- 00541-SCO	NWP	US 285 Trout Creek Bridge Emergency Repairs	Verified Without Special Conditions	Chaffee	СО
SPA-2013- 00433	NWP	Christi and Isaac Dean - Horca	Withdrawn To Become A Standard Permit	Conejos	со
SPA-2013- 00438	NWP	Carrie DeHerrera Conejos River Streambank Protection Project	Verified Without Special Conditions	Conejos	со
SPA-2013- 00398	NWP	Fountain Creek Realignment, Colorado Springs Utilities, El Paso County, Colorado	Verified With Special Conditions	El Paso	со
SPA-2013- 00458-SCO	NWP	Kelker Substation Stormwater Outfall Structure, Sand Creek, Colorado Springs, Colorado	Verified Without Special Conditions	El Paso	со
SPA-2013- 00468-SCO	NWP	Indigo Ranch Stormwater Outfall No. 2, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	со
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	СО
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	со
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	со

SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	со
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	СО
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	СО
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00472-SCO	NWP	USAFA Project No. SABER Contract, Project No. XQPZ 10-0203, Repair Bridge Structures & Culverts	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00476-SCO	NWP	CDOT, Waldo Canyon Watershed Crossing at SH 24	Verified Without Special Conditions	El Paso	со
SPA-2013- 00494-SCO	NWP	Jimmy Camp Creek Interceptor Sewer Phase 3	Verified Without Special Conditions	El Paso	со
SPA-2013- 00508-SCO	NWP	The Falls Event Center	Verified Without Special Conditions	El Paso	со
SPA-2013- 00509-SCO	NWP	Homeless Camp Sediment Removal, Fountain Creek, Manitou Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2013- 00520	NWP	Bridge Repair 10925 West US Hwy 24, El Paso County, Colorado	Verified Without Special Conditions	El Paso	СО
SPA-2013- 00525-SCO	NWP	Colorado Springs Utilities - Bank Stabilization Steel Hollow, Pueblo, Co., Colorado	Verified Without Special Conditions	El Paso	со

SPA-2013- 00539-SCO	NWP	North Rockrimmon Channel Project	Verified Without Special Conditions	El Paso	со
SPA-2013- 00539-SCO	NWP	North Rockrimmon Channel Project	Verified Without Special Conditions	El Paso	со
SPA-2013- 00576-SCO	NWP	City of Manitou Springs Williams Canyon Geotechnical Investigation	Verified Without Special Conditions	El Paso	со
SPA-2013- 00492-SCO	NWP	CDOT US 650 at Bighorn Sheep Canyon Bridge Replacement Project	Verified Without Special Conditions	Fremont	СО
SPA-2013- 00567-SCO	NWP	Florence Dam Intake Work, Arkansas River, Florence, Fremont County, Colorado	Verified Without Special Conditions	Fremont	со
SPA-2013- 00426-SCO	NWP	City of Aurora Headwaters Umbrella Mitigation Bank	Verified Without Special Conditions	Lake	со
SPA-2013- 00559-SCO	NWP	CDOT Region 2 Critical Road Culverts, Several Counties in SE Colorado	Verified Without Special Conditions	Otero	со
SPA-2013- 00477-SCO	NWP	Pringtime Dam Outlet Repair, West Fork of West Beaver Creek, Teller County, Colorado	Verified Without Special Conditions	Teller	со
SPA-2013- 00502-SCO	NWP	CPW-Skagway Reservoir - flume replacement - Beaver Creek, Teller County, Colorado	Verified Without Special Conditions	Teller	со
SPA-2013- 00507-SCO	NWP	North to South Catamount Reservoir Transfer Pipeline, Teller County, Colorado	Verified Without Special Conditions	Teller	со
SPA-2004- 00232	NWP	San Juan Chama Drinking Water Project, Alameda Diversion Dam	Verified With Special Conditions	Bernalillo	NM
SPA-2012- 00066-LCO	NWP	Village of Reserve Water Distribution and Transmission Improvements	Verified Without Special Conditions	Catron	NM
SPA-2013- 00538-LCO	NWP	West Fork Bridge Replacement	Verified Without Special Conditions	Catron	NM
SPA-2013- 00529-LCO	NWP	Bank stabilization repair on the Hondo River - Roswell New Mexico	Verified Without Special Conditions	Chaves	NM

NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
	NWP	NWP BIA, Roadway Re-construction, N55 NWP BIA, Roadway Re-construction, N55	NWP BIA, Roadway Re-construction, N55 Conditions Verified With Special Conditions	NWP BIA, Roadway Re-construction, N55 Conditions Cibola NWP BIA, Roadway Re-construction, N55 Conditions NWP BIA, Roadway Re-construction, N55 Cibola NWP BIA

NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
	NWP	NWP BIA, Roadway Re-construction, N55 NWP BIA, Roadway Re-construction, N55	NWP BIA, Roadway Re-construction, N55 Conditions Verified With Special Conditions	NWP BIA, Roadway Re-construction, N55 Conditions Cibola NWP BIA, Roadway Re-construction, N55 Conditions NWP BIA, Roadway Re-construction, N55 Cibola NWP BIA

			1		
SPA-2013- 00421	NWP	BIA, Roadway Re-construction, N55	Verified With Special Conditions	Cibola	NM
SPA-2013- 00462-ABQ	NWP	Vermejo Park Ranch, Adobe and Little Wall Potential Avulsion Restorations, Vermejo River	Verified With Special Conditions	Colfax	NM
SPA-2013- 00463-ABQ	NWP	Zia Natural Gas, Cimarron Gas Line Replacement, Ponil River	Verified With Special Conditions	Colfax	NM
SPA-2013- 00533-LCO	NWP	Village of Santa Clara - Fellner St. & Cameron Creek Low Water Crossing	Verified Without Special Conditions	Grant	NM
SPA-2013- 00564-LCO	NWP	Hanover Creek Diesel Release	Verified Without Special Conditions	Grant	NM
SPA-2013- 00498-ABQ	NWP	Ranches of Sonterra Sediment Catchment Basin Project in Lincoln County, New Mexico	Verified With Special Conditions	Lincoln	NM
SPA-2013- 00519-ABQ	NWP	Repair of a Drainage Outlet Along Route Z4 on Zuni Pueblo in McKinley County, New Mexico	Verified With Special Conditions	McKinley	NM
SPA-2013- 00561	NWP	Culvert Replacement Chaco Wash	Verified Without Special Conditions	McKinley	NM
SPA-2013- 00505-ABQ	NWP	Canon Bonito Ranch, Canon Bonito Creek Restoration Phase 5	Verified With Special Conditions	Mora	NM
SPA-2013- 00444-ABQ	NWP	USFS Carson NF Placer Creek Headcut Restoration	Verified With Special Conditions	Rio Arriba	NM
SPA-2013- 00452	NWP	Rio Chama Habitat Improvement	Verified With Special Conditions	Rio Arriba	NM
SPA-2013- 00460	NWP	Navajo River Habitat Improvement	Verified With Special Conditions	Rio Arriba	NM
SPA-2013- 00569-ABQ	NWP	Ohkay Owingeh, Llano Ditch, Culvert Extension, McCurdy Road, Rio Arriba County, NM	Verified Without Special Conditions	Rio Arriba	NM
SPA-2009- 00529-DUR	NWP	Animas River Pump Station	Verified Without Special Conditions	San Juan	NM
SPA-2013- 00017-ABQ	NWP	Piojo Ranch Mora River Stream Restoration, Watrous, Mora County	Verified With Special Conditions	San Juan	NM

			I		
SPA-2013- 00209	NWP	Unauthorized Activity, Laurie Street Road Crossing	Verified Without Special Conditions	San Juan	NM
SPA-2013- 00372	NWP	Captain Tom Wash Crossing	Withdrawn	San Juan	NM
SPA-2013- 00497	NWP	NMDOT 170 Bridge Replacement	Withdrawn	San Juan	NM
SPA-2013- 00510	NWP	Largo Wash Cleanup Hazardous	Verified With Special Conditions	San Juan	
SPA-2013- 00562	NWP	Porter Arroyo pipe maintenance	Verified Without Special Conditions	San Juan	
SPA-2013- 00391-ABQ	NWP	Unauthorized Activity- Diversion Dam constructed within Maestas Creek, Rociada, NM	Withdrawn Due To No Permit Required (NPR)		NM
SPA-2013- 00457-ABQ	NWP	Lorenzo Sanchez, Rock Vanes, Gallinas River below Montezuma	Verified With Special Conditions	San Miguel	NM
SPA-2004- 00326	NWP	SANTA ANA PUEBLO-LEVEE REPAIR/ARROYO AGU	Verified With Special Conditions	Sandoval	NM
SPA-2012- 00366-ABQ	NWP	Santo Domingo Priority Site RM 224.6 in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2012- 00366-ABQ	NWP	Santo Domingo Priority Site RM 224.6 in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013- 00169-ABQ	NWP	Santa Ana Priority Site RM 205.8 in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013- 00169-ABQ	NWP	Santa Ana Priority Site RM 205.8 in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013- 00368-ABQ	NWP	Los Milagros Arroyo Stormwater Facilities, Rio Rancho, Sandoval County	Verified With Special Conditions	Sandoval	NM
SPA-2013- 00404-ABQ	NWP	Fenton Lake Dry Hydrant, Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2013- 00568-ABQ	NWP	Pete Yocky Bank Stabilization Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM

SPA-2010- 00480-ABQ	NWP	NMDOT, Galisteo Creek, San Cristoabal Arroyo, NM 41 Bridge Replacements, Santa Fe Coutn, NM	Verified With Special Conditions	Santa Fe	NM
SPA-2012- 00518-ABQ	NWP	Santa Fe County, Santa Fe River, Restoration Project, Siler Rd., Santa Fe County, NM	Withdrawn For Lack Of Applicant Response	Santa Fe	NM
SPA-2012- 00518-ABQ	NWP	Santa Fe County, Santa Fe River, Restoration Project, Siler Rd., Santa Fe County, NM	Withdrawn For Lack Of Applicant Response	Santa Fe	NM
SPA-2013- 00456-ABQ	NWP	Los Alamos County, Guaje Canyon, Road and Waterline Repairs, Santa Fe County, NM	Verified With Special Conditions	Santa Fe	NM
SPA-2013- 00526-ABQ	NWP	BOR, San Ildefonso Pueblo, Rio Grande, Channel Restoration, Santa Fe Count, NM	Verified With Special Conditions	Santa Fe	NM
SPA-2013- 00535-ABQ	NWP	BNSF, Abo Arroyo Tributary, Bridge 7100, Replacement, Torrance County, NM	Withdrawn	Torrance	NM
SPA-2013- 00427-ABQ	NWP	Transwestern Pipeline Company, Erosion and washout of pipeline, Section 7 MP 51.9, Valencia County	Verified With Special Conditions	Valencia	NM
SPA-2013- 00447-ABQ	NWP	Transwestern Pipeline Company, Erosion and washout of pipeline, Section 7 MP 52.8, Valencia County	Verified With Special Conditions	Valencia	NM