

Nationwide Permit Actions
October - December 2015

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2015-00343	NWP	Wheatfield Creek Stream Crossing Renovation	Withdrawn	Apache	AZ
SPA-2015-00369-SCO	NWP	Arkansas River Bank Stabilization Project	Verified Without Special Conditions	Chaffee	CO
SPA-2015-00361	NWP	Bridge Maintenance, Conejos River Overflow Channel, US 285 at MM 7.8	Verified Without Special Conditions	Conejos	CO
SPA-2015-00382	NWP	Conejos County Bridge CR #6	Verified Without Special Conditions	Conejos	CO
SPA-2015-00441	NWP	Union Gold Water Treatment Discharge Pipeline	Withdrawn By Applicant	Conejos	CO
SPA-2007-00271	NWP	El Paso County, Woodmen Road improvements, Colorado Springs, El Paso County, Colorado	Verified With Special Conditions	El Paso	CO
SPA-2015-00377-SCO	NWP	Prebles Meadow Jumping Mouse Habitat Management Project	Verified Without Special Conditions	El Paso	CO
SPA-2015-00379-SCO	NWP	Water Line Replacement, 642 Manitou Ave., Fountain Creek, Manitou Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00380-SCO	NWP	Quail Brush Creek Bank Stabilization and Road Maintenance Project, Colorado Springs, El Paso County, Colorado	Verified With Special Conditions	El Paso	CO
SPA-2015-00380-SCO	NWP	Quail Brush Creek Bank Stabilization and Road Maintenance Project, Colorado Springs, El Paso County, Colorado	Verified With Special Conditions	El Paso	CO
SPA-2015-00383-SCO	NWP	Golden Lane Road Bridge Replacement, Fountain Creek, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00401-SCO	NWP	Crystal Park Road Culvert Replacement Project, Wildcat Gulch, Manitou Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00416-SCO	NWP	I-25 Culvert Flood Damage, Monument Branch, Colorado Springs, El Paso County, Colorado	Verified With Special Conditions	El Paso	CO
SPA-2015-00421-SCO	NWP	Rockrimmon Blvd Culvert Repair, Rockrimmon North Drainage, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00446-SCO	NWP	Black Forest Culverts Replacement Project, Kettle Creek, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2015-00404-SCO	NWP	Williamsburg Waterline Installation Project, Fremont County, Colorado	Verified Without Special Conditions	Fremont	CO

SPA-2014-00476-SCO	NWP	Bypass Flume Replacement, Big Evans Reservoir, Leadville, Lake County, Colorado	Verified With Special Conditions	Lake	CO
SPA-2015-00362	NWP	Gloe Power Run Across Carnero Creek	Verified Without Special Conditions	Saguache	CO
SPA-2015-00394	NWP	City of Crestone Culvert Improvements	Withdrawn Due To No Permit Required (NPR)	Saguache	CO
SPA-2015-00406-SCO	NWP	Gold Camp Road Culvert Replacement, Middle Beaver Creek, Teller County, Colorado	Verified Without Special Conditions	Teller	CO
SPA-2014-00521-LCO	NWP	Catwalk Trail Reconstruction Gila National Forest NM ERFO 207(1)	Verified With Special Conditions	Catron	NM
SPA-2014-00521-LCO	NWP	Catwalk Trail Reconstruction Gila National Forest NM ERFO 207(1)	Verified With Special Conditions	Catron	NM
SPA-2014-00521-LCO	NWP	Catwalk Trail Reconstruction Gila National Forest NM ERFO 207(1)	Verified With Special Conditions	Catron	NM
SPA-2014-00521-LCO	NWP	Catwalk Trail Reconstruction Gila National Forest NM ERFO 207(1)	Verified With Special Conditions	Catron	NM
SPA-2015-00368-LCO	NWP	Enterprise Products Operating LLC - Bank Stabilization in Bosque Draw, Chaves County, New Mexico	Verified With Special Conditions	Chaves	NM
SPA-2015-00289	NWP	Transwestern Pipeline Company Pipeline Recoat Activity Section 6 MP 3.46	Verified Without Special Conditions	Cibola	NM
SPA-2015-00289	NWP	Transwestern Pipeline Company Pipeline Recoat Activity Section 6 MP 3.46	Verified Without Special Conditions	Cibola	NM
SPA-2015-00289	NWP	Transwestern Pipeline Company Pipeline Recoat Activity Section 6 MP 3.46	Verified Without Special Conditions	Cibola	NM
SPA-2015-00431-LCO	NWP	New Mexico State University, Bank Stabilization Tortugas Arroyo	Verified With Special Conditions	Dona Ana	NM
SPA-2015-00193-LCO	NWP	Duck Creek Low Water Crossing in Grant County, New Mexico	Verified Without Special Conditions	Grant	NM
SPA-2015-00411-LCO	NWP	Gila Mesa Association River Crossing Repair	Verified Without Special Conditions	Grant	NM
SPA-2013-00461-ABQ	NWP	Los Alamos Canyon Reservoir Dredging and Access Road Repairs	Verified With Special Conditions	Los Alamos	NM
SPA-2015-00207	NWP	Casamero Lake Low Water Crossing	Verified Without Special Conditions	McKinley	NM
SPA-2015-00320	NWP	Pipeline Erosion Repair Activity on Right of Way, Section 5 MP 39.50, Transwestern Pipeline Company	Verified Without Special Conditions	McKinley	NM
SPA-2015-00320	NWP	Pipeline Erosion Repair Activity on Right of Way, Section 5 MP 39.50, Transwestern Pipeline Company	Verified Without Special Conditions	McKinley	NM
SPA-2015-00402	NWP	J-18 Bridge Replacement with Low Water Crossing on Largo Canyon	Withdrawn	Rio Arriba	NM

SPA-2015-00448-ABQ	NWP	Access Road Hole Fill on Carrizo Canyon	Verified Without Special Conditions	Rio Arriba	NM
SPA-2015-00304	NWP	Pena Blanca Arroyo Stream Stabilization Project	Verified Without Special Conditions	San Juan	NM
SPA-2015-00342	NWP	Crystal Creek Stream Crossing Renovation	Withdrawn	San Juan	NM
SPA-2015-00359	NWP	Animas River Headgate Replacement	Verified Without Special Conditions	San Juan	NM
SPA-2015-00359	NWP	Animas River Headgate Replacement	Verified Without Special Conditions	San Juan	NM
SPA-2015-00374	NWP	Blanco Ditch Crossing #7 Culvert Replacement	Verified Without Special Conditions	San Juan	NM
SPA-2015-00082-ABQ	NWP	Santa Clara Creek and Tributaries Debris Flow Barrier Installation	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00200-ABQ	NWP	Kinder Morgan Pipeline Protection Measures in Penistaja Arroyo in Sandoval County, New Mexico	Withdrawn	Sandoval	NM
SPA-2015-00332-ABQ	NWP	City of Rio Rancho Sonora Road Crossing in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00378-ABQ	NWP	Phase II of the City of Rio Rancho's (CORR) Los Milagros Stormdrain Project in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2015-00415-ABQ	NWP	Geotechnical Drilling at US 550 and Rio Grande A301232	Verified With Special Conditions	Sandoval	NM
SPA-2014-00145-ABQ	NWP	City of Santa Fe Arroyo Chamisos Stabilization and Restoration	Verified With Special Conditions	Santa Fe	NM
SPA-2015-00371-ABQ	NWP	Rio Nambe Automated Flood Warning System Installation	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00396	NWP	Tesuque Sewer Line Replacement at Arroyo Cuma	Verified Without Special Conditions	Santa Fe	NM
SPA-2015-00405	NWP	NM 169 at MM 30.5 bank stabilization for roadway protection	Verified With Special Conditions	Socorro	NM
SPA-2014-00536-ABQ	NWP	Weimer Hills Water Distribution Line, Taos, Taos County, New Mexico	Withdrawn By Applicant	Taos	NM
SPA-2015-00230-LCO	NWP	Loop 375 Border Highway Extension WAT 3	Verified Without Special Conditions	El Paso	TX
SPA-2015-00230-LCO	NWP	Loop 375 Border Highway Extension WAT 3	Verified Without Special Conditions	El Paso	TX
SPA-2015-00426-LCO	NWP	BNSF Bridge 7300-1150.000 Replacement	Verified With Special Conditions	El Paso	TX