

Nationwide Permit Actions
January - March 2016

DA Number	Action Type	Project Name	Closure Method	County	State
SPA-2016-00042-SCO	NWP	Phillips 66 refinery site clean-up	Verified Without Special Conditions	Alamosa	CO
SPA-2016-00051-SCO	NWP	Lake Hasty Fishing Pier	Verified Without Special Conditions	Bent	CO
SPA-2016-00060-SCO	NWP	Noah's Ark White Water Rafting Co. Bank Stabilization	Verified Without Special Conditions	Chaffee	CO
SPA-2016-00111-SCO	NWP	Cottonwood Creek Bank Stabilization	Verified Without Special Conditions	Chaffee	CO
SPA-2015-00441	NWP	Union Gold Water Treatment Discharge Pipeline	Verified Without Special Conditions	Conejos	CO
SPA-2016-00036	NWP	SH 17 Culvert Maintenance at MM 3.18, Conejos County	Verified Without Special Conditions	Conejos	CO
SPA-2015-00116-SCO	NWP	Rockrimmon Blvd. Bridge Replacement Project, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2016-00016-SCO	NWP	Fort Carson Housing Kiowa East Detention Pond Maintenance	Verified Without Special Conditions	El Paso	CO
SPA-2016-00032-SCO	NWP	Stratmoor Aerial Sewer Crossing, Stratmoor Hills, Colorado Springs, El Paso County, Colorado	Verified Without Special Conditions	El Paso	CO
SPA-2016-00043-SCO	NWP	Jones and Log Road Channel Repair	Verified Without Special Conditions	El Paso	CO
SPA-2016-00044-SCO	NWP	Meridian Road Bridge Deck Replacement Project (EPC 0427-11.55A)	Verified Without Special Conditions	El Paso	CO
SPA-2016-00045-SCO	NWP	North Calhan Highway Bridge Deck Replacement Project (EPC 0129-12.20A)	Verified Without Special Conditions	El Paso	CO
SPA-2016-00046-SCO	NWP	Peyton Highway Bridge Deck Replacement Project (EPC 0463-19.90A and EPC 0463-20.00A)	Verified Without Special Conditions	El Paso	CO
SPA-2016-00046-SCO	NWP	Peyton Highway Bridge Deck Replacement Project (EPC 0463-19.90A and EPC 0463-20.00A)	Verified Without Special Conditions	El Paso	CO
SPA-2016-00076-SCO	NWP	City of Colorado Springs - culver replacement	Verified Without Special Conditions	El Paso	CO
SPA-2016-00077-SCO	NWP	Hewlett-Packard Enterprise (HPE), CB&I Environmental & Sustainability, Inc. Sewer Line Maintenance Project	Verified Without Special Conditions	El Paso	CO
SPA-2016-00078-SCO	NWP	Green Mtn Falls/ Chipita Park Fire Dept.	Verified Without Special Conditions	El Paso	CO
SPA-2016-00090-SCO	NWP	South Douglas Creek at Sinton Pond Sanitary Sewer Realignment and Stream Stabilization Project	Withdrawn To Become A General Permit (RGP, PGP)	El Paso	CO
SPA-2016-00098-SCO	NWP	City of Colorado Springs - Mesa Drive Bridge	Verified Without Special Conditions	El Paso	CO
SPA-2016-00100-SCO	NWP	BN&SF RR bridge maintenance	Verified Without Special Conditions	El Paso	CO

SPA-2016-00104-SCO	NWP	Wellfield Road Culvert Replacement Project	Verified Without Special Conditions	El Paso	CO
SPA-2016-00105-SCO	NWP	Zero Discharge Transfer Line Concrete Block Mat Protection Project	Verified Without Special Conditions	El Paso	CO
SPA-2016-00107-SCO	NWP	Bear Creek Channel Stabilization Project	Verified With Special Conditions	El Paso	CO
SPA-2016-00054-SCO	NWP	Starr Placer Commercial Development Project	Verified Without Special Conditions	Lake	CO
SPA-2016-00037-SCO	NWP	I-25 Concrete Box Culverts, Thomas Phelps Creek, Pueblo, Pueblo County, Colorado	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2016-00041-SCO	NWP	Pueblo County Roads	Verified Without Special Conditions	Pueblo	CO
SPA-2015-00438	NWP	El Encantada Ranch Streambank Stabilization	Withdrawn	Rio Grande	CO
SPA-2015-00438	NWP	El Encantada Ranch Streambank Stabilization	Verified Without Special Conditions	Rio Grande	CO
SPA-2015-00438	NWP	El Encantada Ranch Streambank Stabilization	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00071-SCO	NWP	Flying W Ranch	Verified Without Special Conditions	Rio Grande	CO
SPA-2016-00085-LCO	NWP	Erosion Repair and Pipeline Protection, Section 9 MP 10.59 Wagner Ranch, Transwestern Pipeline Company	Verified With Special Conditions	Chaves	NM
SPA-2015-00444	NWP	George Hanosh Bridge Repair, City of Grants, NM	Verified With Special Conditions	Cibola	NM
SPA-2009-00525-ELP	NWP	La Mancha Wetland Creation Mesilla, Dona Ana County	Verified With Special Conditions	Dona Ana	NM
SPA-2016-00015-LCO	NWP	Eddy County Roadway Improvement CR # 29 Crossbuck Road	Verified With Special Conditions	Eddy	NM
SPA-2016-00031	NWP	El Rito Creek River Stewardship Restoration Project, Guadalupe County, NM	Verified With Special Conditions	Guadalupe	NM
SPA-2015-00399	NWP	Allison Road Realignment over the Rio Puerco	Verified Without Special Conditions	McKinley	NM
SPA-2016-00040	NWP	Allison Road Realignment over the Rio Puerco	Withdrawn	McKinley	NM

SPA-2016-00048-ABQ	NWP	Navajo River Municipal Water Diversion Maintenance and Bank Stabilization Dulce	Verified With Special Conditions	Rio Arriba	NM
SPA-2016-00048-ABQ	NWP	Navajo River Municipal Water Diversion Maintenance and Bank Stabilization Dulce	Verified With Special Conditions	Rio Arriba	NM
SPA-2016-00065-ABQ	NWP	Rio Ojo Caliente Bank Stabilization at Acequia del Gavilan Diversion Structure	Verified With Special Conditions	Rio Arriba	NM
SPA-2015-00381	NWP	Navajo Route N57 State 5+425	Verified Without Special Conditions	San Juan	NM
SPA-2015-00392	NWP	Pine Marina Complex Expansion Navajo Lake State Park	Verified With Special Conditions	San Juan	NM
SPA-2015-00423	NWP	Cofferdam for Inspection and Rehabilitation Fruitland Diversion	Verified Without Special Conditions	San Juan	NM
SPA-2015-00306-ABQ	NWP	Pueblo of Sandia Habitat Features Creation and Modification Project	Verified With Special Conditions	Sandoval	NM
SPA-2015-00307-ABQ	NWP	Rio Rancho Open Space Habitat Restoration Project, Phase II	Verified With Special Conditions	Sandoval	NM
SPA-2015-00409	NWP	Milepost 284 Pipeline Exposure Repair	Verified With Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00420-ABQ	NWP	Santa Fe National Forest Fish Habitat Restoration Project in the Jemez River, Sandoval County, New Mexico	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM

SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2015-00440	NWP	Peralta Canyon Flood Control Facilities Maintenance at Cochiti Pueblo	Verified Without Special Conditions	Sandoval	NM
SPA-2016-00025-ABQ	NWP	Red Rocks Dam Rehabilitation Project on Pueblo of Jemez Lands in Sandoval County, New Mexico	Verified With Special Conditions	Sandoval	NM
SPA-2016-00039	NWP	City of Rio Rancho Idalia Road La Barranca Tributary Crossing	Verified With Special Conditions	Sandoval	NM
SPA-2015-00241	NWP	Nambe NP 102 West Low Water Crossing	Withdrawn For Lack Of Applicant Response	Santa Fe	NM
SPA-2015-00447-ABQ	NWP	Guaje Canyon Road Mitigation Project	Verified With Special Conditions	Santa Fe	NM
SPA-2015-00447-ABQ	NWP	Guaje Canyon Road Mitigation Project	Verified With Special Conditions	Santa Fe	NM
SPA-2015-00447-ABQ	NWP	Guaje Canyon Road Mitigation Project	Verified With Special Conditions	Santa Fe	NM
SPA-2016-00092-ABQ	NWP	Boat Ramp Improvements at Elephant Butte State Park	Verified Without Special Conditions	Sierra	NM
SPA-2016-00092-ABQ	NWP	Boat Ramp Improvements at Elephant Butte State Park	Verified Without Special Conditions	Sierra	NM
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX
SPA-2015-00182-LCO	NWP	Comanche Trail Pipeline to the Rio Grande and Directional Bore Beneath the Rio Grande El Paso Texas	Verified Without Special Conditions	El Paso	TX